
Breakthrough Improvement With Excel Reducing Defects









Focus

Improve

Sustain


Honor

Summarize



PivotTable


Chart



Pareto Chart

_ .

5 Whys?



Cause-Effect Diagram



Comparing Control Charts

Verify

Categorize


Monitor



Breakthrough Improvement With Excel Reducing Variation










Focus

Improve

Sustain

Honor



Capability

